

# ProWingcar × Pro Inspection Report

2011 Kia K5

Stock: WCRB1HGBBS · VIN: AABB2011AAB505070

Overall Grade: A (100%)

Published: 2026-05-21

## Category Grades

Category	Score	Grade
body	100%	A
chassis	94%	A
electrical	100%	A
engine	100%	A
interior	100%	A
transmission	100%	A
underbody	100%	A

## Inspection Checklist

Category	Item	Result	Notes
engine	☐ ☐ ☐	PASS	
engine	☐☐ ☐	PASS	
engine	☐ ☐	PASS	
engine	☐ ☐☐	PASS	
engine	☐ ☐	PASS	
engine	☐ ☐	PASS	
engine	☐☐	PASS	
engine	☐	PASS	
engine	☐ ☐	PASS	
engine	☐ ☐	PASS	
transmission	☐ ☐	PASS	
transmission	☐ ☐	PASS	
transmission	☐☐	PASS	
transmission	☐ ☐	PASS	
transmission	☐ ☐	PASS	
body	☐ ☐	PASS	
body	☐ ☐	PASS	
body	☐	PASS	
body	☐	PASS	
body	☐ ☐	PASS	
body	☐	PASS	
chassis	☐☐☐	PASS	

Category	Item	Result	Notes
chassis	□□□□	PASS	
chassis	□□	PASS	
chassis	□□□	ATTENTION	
chassis	□□□□	PASS	
electrical	□□□	PASS	
electrical	□□	PASS	
electrical	□□□	PASS	
electrical	□□	PASS	
interior	□□	PASS	
interior	□□□□	PASS	
interior	□□ □□	PASS	
interior	□□□□	PASS	
underbody	□□ □□	PASS	
underbody	□□	PASS	
underbody	□□□□	PASS	